

SUPERSENSOR



DESCRIPTION

SUPERSENSOR is a waterborne acrylic resin which is a very high strength adhesive for use with vinyl tiles, vinyl sheet, carpet tiles and rubber based acoustic matting.

SUPERSENSOR is suitable for such substrates as timber subfloors, particle board, plywood flooring of approved grades, dry concrete floors and on old vinyl.

PREPARATION

Floors must be surface dry, free of moisture in the substrate, clean, sound, smooth and free of dirt, wax, grease, oily residues, mould, algae, fungi and any loose materials. Uneven, wood float finish or damaged concrete floors should be repaired with smooth lay thin screeds. Old vinyl must be sanded. Surface preparation of a substrate should also be undertaken with referral to AS1884.

Concrete that have had previous coatings applied to them should be ground off to remove coatings. Water blasting should follow to remove all dusts and loose material. Allow to dry before proceeding.

CONCRETE: Apply one coat **PLICRETE** or **SCREEDBOND/CEMENT** as a primer at a rate of 4-5m²/litre. Apply two coats if concrete is subject to rising moisture or is highly porous.

IRON AND STEEL: Remove any rust before painting iron or steel. Use **CORROPEL** at the rate of 6-8m²/litre/coat on bare or rust effected iron or steel. For unsound painted surfaces, remove the paint and apply **CORROPEL** as above. One coat of **CORROPEL** is usually sufficient. If two coats are necessary, allow at least four hours @25°C before applying the second coat.

PARTICLE BOARD, PLYWOOD, TIMBER SUBFLOORS: Apply one coat of GENPRIME at a rate of 8-10m²/litre. All timber substrates should be permanently free of moisture.

All primers should be allowed to dry thoroughly before application of **SUPERSENSOR**. Refer to individual product sheet for further information.

APPLICATION

Apply adhesive to floor with a V-shaped fine spreader or roller coater. Suitable equipment is a wide coarse-hair roller with mobile cover. Allow the adhesive to become dry and tacky before applying the covering. When first spread, **SUPERSENSOR** is a milky colour. When dry, it changes to a fawn colour and becomes tacky. This tack remains in the region of 24 hours providing the adhesive remains free from dust and moisture depositing on it.

PRECAUTIONS

Do not allow the contents to freeze. This adhesive should not be used in areas where hydrostatic water pressure, excessive water by capillary action or ponding water may exist. See AS1884 for a guide to ascertaining this. For best results, apply at minimum 20°C for adhesive floor covering and subfloor. Relative air humidity should in the region of 25-65%. The use of large circulating fans is an effective method of speeding up the adhesive's drying time.

COVERAGE

Vinyl tiles and sheet:

1-1.6mm V-notchings 8-10m²/litre.

Acoustic sheet:

3-4mm notched trowel 3-4m²/litre.

Coverage rates are a guide only. Tests should be carried out to determine exact coverage based on substrate conditions.

FACTORY
16 GOONGARRIE STREET
BAYSWATER WA 6053
AUSTRALIA

POSTAL
PO BOX 385
BAYSWATER WA 6933
AUSTRALIA

TELEPHONE
TEL. (08) 9378 2022
FAX. (08) 9377 2575
MOB. 0418 956 860

IDENTIFICATION
PAGE 1 of 2
ISSUE: JULY 2011
REF: SSSR

QUINDALUP HOLDINGS PTY LTD (A.C.N. 009 026 386) AS TRUSTEE FOR CALMARC FAMILY TRUST (ABN 18 340 289 669)
This information is offered solely for the customer and/or specifier for their consideration, investigation and verification. The suggestions mentioned herein should be fully assessed prior to application. No warranty or implied liability is given for any recommendations, advice, suggestions made by Calmarc Chemicals or representatives, agents or distributors for the conditions of use and labour for the products which are beyond our control. Catalogue or specification contents may change from time to time without notice. SDS is available.

SUPERSENSOR



CLEAN UP

Wet adhesive should be removed with water. When dry, clean with **MARCMOVE**.

PACK SIZES

SUPERSENSOR is sold in packs of 10 litres.

STORAGE

SUPERSENSOR should be stored undercover away from foodstuffs and in a cool area between 5-30°C. The lid on the container should be firmly fitted.

SAFETY

SUPERSENSOR is a waterborne product. It is advisable to have air movement over the working area. For skin contact, wash off **SUPERSENSOR** using soapy water. With eye contact rinse the eye(s) with water for 15 minutes and seek medical advice. **SUPERSENSOR** is not a hazardous good as defined by Safe Work Australia.

Contents are guaranteed to be free from defect in materials and workmanship. Recommendations for use of this product are based on experience and tests believed to be reliable and may as such be considered as a guide. Since the use of the product is beyond our control, we do not assume any responsibility for the results. We accept no liability whatsoever for consequential damages no matter what the cause.

FACTORY
16 GOONGARRIE STREET
BAYSWATER WA 6053
AUSTRALIA

POSTAL
PO BOX 385
BAYSWATER WA 6933
AUSTRALIA

TELEPHONE
TEL. (08) 9378 2022
FAX. (08) 9377 2575
MOB. 0418 956 860

IDENTIFICATION
PAGE 2 of 2
ISSUE: JULY 2011
REF: SSSR

QUINDALUP HOLDINGS PTY LTD (A.C.N. 009 026 386) AS TRUSTEE FOR CALMARC FAMILY TRUST (ABN 18 340 289 669)
This information is offered solely for the customer and/or specifier for their consideration, investigation and verification. The suggestions mentioned herein should be fully assessed prior to application. No warranty or implied liability is given for any recommendations, advice, suggestions made by Calmarc Chemicals or representatives, agents or distributors for the conditions of use and labour for the products which are beyond our control. Catalogue or specification contents may change from time to time without notice. SDS is available.